

BUILDING SAFETY CERTIFICATE

It is certified that the existing building **DAV NCL Public School, at Block- B Area, Gorbi, Distt.- Singrauli, (M.P.)** is having block(s)/Floor(s) as per details below.

Detail of Block (S) in School	Block (1) Academic Block	Block (2) Administrative Block
No. of Floor (S) in the Block	02 Floors (01.) Ground Floor (02.) First Floor	01 Floor (01.) Ground Floor


The building is owned /occupied **DAV NCL Public School, at Block-B Area, Gorbi, Distt. Singrauli, (M.P.)** have complied with the Building is Sound in accordance with National Building code Rules, and verified by the So officers concerned of **Public Work Department** On **15May 2024** in the presence of **Mr. Amitabh Srivastava**,^{Manager, P.W.D.} and that the building/premises is fit for occupancy for running school with effect from **15/May/2024** for a period of **One** year in accordance with rule and subject to compliance of the specific conditions as appended.

01. Periodical inspection of school building must be ensured.

02. Time to time maintains of school building must be ensured.

Issued on: 15 May 2024 at:-

*Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

 Executive Engineer
 P.W.D. Div Singrauli
 Distt.- Singrauli (M.P.)

Name:..VINOD...KUMAR...CHAURASIYA...

Designation:..Executive Engineer.....

Name & Address of department/office..P.W.D Div Singrauli.....